

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Fig. 1A




Fig. 1B




Fig. 2




Fig. 3A




Fig. 3B




Fig. 4A




Fig. 4B




Fig. 4C




Fig. 4D




Fig. 4E




Fig. 4F




Fig. 4G




Fig. 5





Fig. 6






Fig. 7A




Fig. 7B

Fig. 8




Fig. 9





Fig. 10



- ① CHARACTERISTIC IMPEDANCE OF PHASE MATCHING LINE IS GREATER
THAN THAT OF EXTERNAL CIRCUIT
- ② CHARACTERISTIC IMPEDANCE OF PHASE MATCHING LINE IS SMALLER
THAN THAT OF EXTERNAL CIRCUIT

ENLARGED PASS BAND REFLECTION CHARACTERISTIC OF RECEIVE PORT




Fig. 11A







Fig. 11B



- ① NO GROUND BETWEEN TX/RX LINES AND
PHASE MATCHING LINE
- ② GROUND EXISTS BETWEEN TX/RX LINES
AND PHASE MATCHING LINE

Fig. 13A

121

136




Fig. 13B

122




Fig. 13C

123




Fig. 13D

126




Fig. 14




Fig. 15A




Fig. 15B




Fig. 16

